



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D5617-3
Job Sheet 198656



Part No: D5617-3

Job Qty: 3 pcs

Part Name: Clamp



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 8/1/19

Job Tracking No:

Due Date: 8/9/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: D5617 REV.PC3 IPP REV:A 19.07.30 NEW ISSUE DD VERF:DP

Ship Via:

Bill of Materials



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S211139



Part: D5617-3

Job No: 198656

Serial No/Batch: S211139

Revision: PC3

Inspector:

Exp Date:

Instructions: Various STC's

Date: 09/05/19

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Welded Assy-1	3 pcs	8/9/19	8/9/19	0.00	0.38	Large Fab - 1		<i>M</i>
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		
							Large Fab - 11 (Various)		
110	QC 5	3 pcs	8/9/19	8/9/19	0.00	0.00	QC 5 - 10		<i>EL</i>
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
							QC 5 - 61		
							QC 5 - 81		
120	Packaging 3-1 - Stock - B4B	3 pcs	8/9/19	8/9/19	0.00	0.00	Packaging 3 - 1 - B4B		<i>EL</i>
							Packaging 3 - 2 - B4B		
							Packaging 3 - 3 - B4B		
							Packaging 3 - 4 - B4B		
							Packaging 3 - 5 - B4B		
130	QC 21 - SA	3 pcs	8/9/19	8/9/19	0.00	0.00	QC 21 - SA - 21		<i>DAS</i> <i>21</i> <i>8-89</i>
							QC 21 - SA - 70		
							QC 21 - SA - 53		

Part Op 100 - 1- Install clamp to 3.15" extrusion 2-CUT PARTS TO DIMENSIONS SHOWN. REMOVE 1.80" MATERIAL FROM
Descriptions: CLAMP BAND.

110 - QC5- Inspect part completeness to step on W/O

120 - Identify as per dwg & Stock Location: *W/O*

130 - QC21- Final Inspection - Work Order Release

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D5616-3	Supra Heavy Duty Hose Clamp Stainless Steel, W4 79-85	3 pcs (1 ea)	100-Large Fab - Welded Assy-1	<i>S205015</i>

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Welded Assy-1	D5616-3	3	3	0